Navajo Abandoned Uranium Mine

Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

Emmett Lee No. 3 AUM Site

Navajo AUM Western Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.599.1111

January 2011

Part I **Site Identification, Location and Status** Site Names and ID numbers as applicable Mine ID: 542 Map ID: W122 **CERCLIS:** NNN000909122 Navajo Abandoned Mine Land Reclamation Program: NA-0198 Local name / Aliases: Julia Semallie common pit; Emmet Lee #3; E. Lee #3 **Chapter and local area:** Coalmine Mesa Chapter County: Coconino State: Arizona **Lat/Long:** 35.6410809339 N / -111.275635037 W **Nearby road and highway:** Indian Route 6730 **Local Post Office:** Cameron, AZ Surface Land Status: check one or more and provide ownership and contact information below **Tribal Trust Land Public lands Private Tribal Fee Land Bureau of Land Mgmt Allotment** State Fee land **Subsurface Mineral Rights:** No information on subsurface mineral rights ownership was found in the EPA/AUM Database. Claim and operator information:

The mine site surface land status is classified as Tribal Trust Land. Historical documents showed the operator of the mine as the Mescalero Mining Company from 1957 to 1958. No additional ownership / lease information was identified in the EPA/AUM database.

Number of residential structures within 200 feet of mine: None

Estimated volume of mine waste onsite: None

Part II Summary of radiological readings

Highest gamma radiation measurement:

42,899 counts per minute (cpm)

Describe any other radiological measurements:


A total of 2,287 gamma radiation measurements were collected from the mine site, ranging from 11,985 cpm to 42,899 cpm. The measurements collected at the reclamation caps were found at a maximum level of approximately 25,000 cpm, and in the eroded area of the eastern reclamation cap at a maximum level of approximately 40,000 cpm. The measurements are represented in Figures 1 and 2.

Background Readings: 13,707 cpm

Background Average: 13,707 cpm

Distribution Chart and Statistics:

The following chart and statistics were generated by ESRI ArcGIS 9.3.1, and show the general distribution of the site gamma radiation measurements. The horizontal X axis represents the gamma radiation reading levels in cpm (lowest levels to the left). The vertical Y axis represents the frequency of each gamma radiation level.



 Count:
 2287

 Minimum:
 11985,00000

 Maximum:
 42899,00000

 Sum:
 36270937,00000

 Mean:
 15859,61390

 Median:
 14688,00000

 Standard Deviation:
 3609,32467

Part III Status of Reclamation and Mine Waste

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: Yes Waste Pile onsite: No

NAMLRP Project Number: NA-0198

NAMLRP Mine features: 1 None

The following information was obtained from field observations collected during the 2010 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

Observed	reclamation	work	and	status:
A -124				

Adits None

Waste Piles None

Pits None

Shafts None

Other Debris and Mine Features

2 reclamation caps, shared with site #154: western cap 1000' x 300'; eastern cap 400' x 100', both made of grey material

Part IV

Site observations and Environs

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

0 to 200 feet: None

200 feet to 0.25 mile: Livestock corral used for cattle, approximately 250' W of site

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None

200 feet to 0.25 mile: None

Levels measured around the perimeter(s) of the identified structure(s):

Background levels near corral

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

0 to 0.25 miles: Pond area behind livestock corral, approximately 500' E of the site

0.25 miles to 4 miles: Little Colorado River Basin approximately 2 mi W of the site

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

None observed

Known Site History: include information from interviews with Chapter officials and residents. Note information on mine ownership, type of mining operation, period of operation, known amount of production, and any other information as provided.

Emmett Lee No. 3 mine consists of an area of 48,456.94 m². The mine was identified as being operational from 1957 to 1962. Historical documents showed the operator of the mine as the Mescalero Mining Company from 1957 to 1958. While operational, the mine had a total production volume of 229 tons. The Emmett Lee No. 3 and Julia Semallie (154) sites reportedly mined from a single common pit. No other historical information or any additional ownership / lease information was identified in the EPA/AUM database.

Part V Response Action Summary

Summary of Evaluation Factors:

Accessibility:

Was the mine easily accessible to potential human activity? Yes

Radiological Measurements:

Were any gamma radiation measurements collected at the mine greater than two times the site-specific background levels?

Yes

Waste Piles:

Were any unreclaimed waste piles observed at the mine with gamma radiation measurements greater than two times the site-specific background levels? No

Structures:

Were any structures observed within 200 feet of the mine?

No

Potential Drinking Water Sources:

Were any potential drinking water sources observed within 4 miles of the mine? Yes

Reclamation:

Was the mine reported to be previously reclaimed, or did the mine appear to be reclaimed?

Yes (two reclamation caps)

Part VI Photos



Photo 1. Emmett Lee No. 3 mine site



Photo 2. Emmett Lee No. 3 mine site, reclamation cap



Photo 3. Emmett Lee No. 3, livestock corral 250' west of site



Photo 4. Emmett Lee No. 3, livestock corral pond 500' west of site


Name:

Part VII Contacts Reports and Information

Stanley Edison (928) 871-6861

Eugene Esplain (928) 871-7331					
Title or official role (if any) Navajo EPA Superfund Program					
Address PO Box 2946, Window Rock, AZ 86515					
Information provided <u>Lead Regulatory Agency</u>					
Name					
Title or official role (if any)					
Address					
Telephone number					
Information provided					
Name					
Title or official role (if any)	_				
Telephone number	_				
Information provided					
Name					
Title or official role (if any)	_				
Telephone number	_				
Information provided					

Figure 1 - Gamma Radiation Measurements, Above Two Times Background Emmett Lee No. 3 (542) **Coalmine Mesa Chapter, Navajo Nation**




> 2X Background

Gamma survey conducted 11/2010 Measured as counts per minute (cpm)

Average background 13,707 cpm


Figure 2 - Gamma Radiation Measurements Emmett Lee No. 3 (542) Coalmine Mesa Chapter, Navajo Nation



Legend

Gamma Radiation Measurements

- 0 10,000
- 10,000 15,000
- 15,000 20,000
- 20,000 50,000
- 50,000 100,000
- > 100,000



Gamma survey conducted 11/2010 Measured as counts per minute (cpm)

Average background 13,707 cpm

